

SMOOTH SURFACE

TRY THESE TIPS FOR A SMOOTH SURFACE ON YOUR CASTING.

- To ensure that tight corners receive coverage, paint the surface of your mold with the same Razzo material you plan to pour into your mold.
- Immediately after pouring, pinch the edges of the mold to release trapped air.
- Use a toothpick to release air bubbles that are close to the surface.
- 4 Tap the sides of your mold to release air bubbles, or lift the mold and gently drop it onto a flat surface.









